

1538

G-000-1005.11

**U.S. DEPARTMENT OF ENERGY FEED MATERIALS PRODUCTION CENTER  
REMEDIAL INVESTIGATION/FEASIBILITY STUDY COMMUNITY MEETING  
FEBRUARY 20, 1990**

**02/20/1990**

**WMCO**

**13**

**PRESENTATION**


**PUBLIC**

**U. S. DEPARTMENT OF ENERGY  
FEED MATERIALS PRODUCTION CENTER  
REMEDIAL INVESTIGATION / FEASIBILITY STUDY**

**Community Meeting  
February 20, 1990**

**REMOVAL ACTION UPDATE**

**Pat Hopper, WMCO  
Manager, Environmental Remedial Actions Project**



1037.1

## DEFINITIONS

**A Removal Action Is a Near-Term Cleanup Which Is Initiated During the Process of Identifying the Ultimate Final Remediation**

**An Engineering Evaluation/Cost Analysis (EE/CA) Is an Analysis of Alternatives for a Removal Action**

## STATUS OF FOUR REMOVAL ACTIONS

- **Contaminated Water Beneath FMPC Buildings**
- **Waste Pit Area Storm Water Run-Off Control**
- **South Plume**
- **K-65 Silos**

## WASTE PIT AREA STORM WATER RUN-OFF CONTROL

- **Analysis of Alternatives in Progress (EE / CA)**
- **Regulator and Public Review Expected in May, 1990**

## **SOUTH PLUME REMOVAL ACTION**

- **Analysis of Alternatives in Progress (EE / CA)**
- **Regulator and Public Review Expected in April, 1990**

## **CONTAMINATED WATER BENEATH FMPC BUILDINGS**

- **Three Pumps Installed Inside Plant 6**
- **5300 Gallons of Water Removed and Treated**
- **Boring Program Has Identified Two New Pockets of Water Found Near Plant 9 and Plant 2/3**

## **K-65 SILOS**

- **Structural Integrity Review**
- **Risk Assessment**
- **Alternatives Analysis**
- **Resampling Plans**

# **K-65 STRUCTURAL INTEGRITY REVIEW: CONCLUSIONS**

**(Performed by Bechtel National, Inc.)**

- **Dome Not in Immediate Danger of Collapsing**
- **Exact Remaining Life of Silos Cannot be Calculated**
- **Dome Would Likely Collapse if Hit Directly by Tornado**
- **Confirmed That Contents of Silos and Berms Should be Removed Simultaneously**

## **K-65 RISK ASSESSMENT**

**(Being Performed by University of Cincinnati)**

**Focus:**

- **Probability of Potential Causes of Failure Happening**
- **Risk to Public Health and Environment**

# **K-65 RESAMPLING PLANS**

- **Reason For Resampling**
- **Experienced Sampling Team Established**
- **Previous Samples Being Analyzed**
- **Camera Inspection of Contents**
- **Resampling Using Modified Vibracore Device**
- **Back-up Method Being Designed**

## **SUMMARY**


- **Technical Challenge of K-65 Sampling**
- **Work Plan and Schedule are Achievable**

**U. S. DEPARTMENT OF ENERGY  
FEED MATERIALS PRODUCTION CENTER  
REMEDIAL INVESTIGATION / FEASIBILITY STUDY**

**Community Meeting  
February 20, 1990**

**RI / FS UPDATE**

**Bob Galbraith  
Senior Geologist, IT**



1037.11a

# **FEASIBILITY STUDY UPDATE**

## **REMEDIAL INVESTIGATION UPDATE**

### **PURPOSE**

- **Provide Update of Field Activities at Suspect Areas, Production Area, and Regional Aquifer**
  - **Activities**
  - **Findings**
  - **Significance**
  - **Response actions**

### **SUSPECT AREAS INVESTIGATION**

- **Geophysical and Radiation Walkover Surveys**
  - **Almost No Anomalies Found**
- **Trenching Program Completed**
- **Borings to Be Completed in**
  - **Waste water treatment area**
  - **Laboratory equipment burial pits**
  - **Southfield, Area 1 pits**



# PRODUCTION AREA INVESTIGATION

- Borings Inside Plant 9 and Pilot Plant
- Data Maps Are Being Prepared For:
  - Water table elevations by month
  - Average uranium in perched water
  - Uranium in soil at five depths

## PLANT 2 / 3

### Reasons For Boring / Piezometer Placement:

- This Plant Area Processed Soluble Forms of Uranium and Other Radionuclides / Chemicals
- "Acid Brick" Floors May Have Leaked
- The Presence of Floor Drains and Sumps
- The Presence of Large Above-ground Storage Tanks

### Expected Findings:

- High Levels of Uranium if Perched Groundwater Is Present
- Possible Presence of Other Radionuclides and Chemicals in Perched Groundwater

## **PLANT 2 / 3 (Cont'd)**

### **Significance of Findings:**

- **Uranium Levels Were Found Where Expected**
- **Other Radionuclides and Chemicals Detected in Some Piezometers Can Be Related to Nearby Storage or Production Facilities**

### **Follow-Up Actions:**

- **Continue Data Analysis to Define Any Continuing Releases**
- **Install Additional Borings / Piezometers, as Appropriate**
- **Prepare Work Plan to Develop Removal Actions for Perched Groundwater**

## **PLANT 9**

- **Piezometer Placed in Area Due to Nearby Sump and Likely Presence of Soluble Uranium**
- **Uranium Concentration: 696,000 ppb in Perched Water**
- **Likely Cause Is Overflow From Sump**

## **SOUTH PLUME WELLS**

### **Expected Findings:**

- **Uranium Concentration in Well 2125 up to 200 ppb  
Due to Proximity to Paddy's Run and Industrial  
Pumping Wells**
- **Uranium Concentration in Well 2128 Less Than 30 ppb  
(West of Main Plume)**

### **Actual Observations:**

- **Well 2125 = 66 ppb**
- **Well 3125 = 86 ppb**
- **Well 2128 = 8 ppb**
- **Well 3128 = 3 ppb**

## **SOUTH PLUME WELLS (Cont'd)**

### **Significance of Findings:**

- **Demonstrates Consistency Between Actual Measurements  
and Model Predictions**
  - **Confirms current understanding of sources and migration  
pathways**
  - **Provides confidence in model**
  - **Model can be used for predicting future conditions and  
for evaluating remedial actions**
  - **Allows definition of final step in field program in this  
area**

## **SOUTH PLUME WELLS (Cont'd)**

1538

- Install Deeper Well at Location 125 to Confirm Bottom of Plume
- Install Well West of Paddy's Run to Confirm Western Limit of Plume
- Improve the Model Based on Latest Findings

## **SOUTHFIELD WELLS**


### **Expected Findings:**

- Difficult to Predict - Purpose of Wells Was to Help Resolve Various Uncertainties
- Reasons:
  - Suspected source located nearby in Southfield Area
  - Located at a transition in groundwater flow patterns

## **ACTUAL OBSERVATIONS**

<b><u>When Sampled</u></b>	<b><u>Well 2045</u></b>	<b><u>Well 2046</u></b>
Round 4 (Jan. 1989)	283 ppb	309 ppb
Round 5 (May 1989)	291 ppb	851 ppb
Round 6 (June 1989)	341 ppb	232 ppb

# HYDROGRAPH AND TOTAL URANIUM DATA<sup>38</sup> FOR WELL CLUSTER AT LOCATION 049



## SOUTHFIELD WELLS (Cont'd)

### Significance of Findings:

- Unusually Large Value in Well 2046 Could Be Due to Extremely Wet Conditions
- Presence of a Local Source Not Supported by Recently Completed Southfield Investigation
- Source May Be Historic Releases From Paddy's Run
- Raises Concern that a Similar Plume May Be Present East of Storm Sewer Outfall Ditch

## **SOUTHFIELD WELLS (Cont'd)**

### **Follow-Up Actions:**

- **Deeper Wells Will Be Installed Here to Determine the Depth of Uranium Contamination**
- **Additional Monitoring Wells Will Be Installed South of These Wells to Evaluate the Theory of Historic Sources in Paddy's Run**
- **Additional Wells Will Be Installed East of the Storm Sewer Outfall Ditch in Case a Similar Plume Originated From the Ditch and Flowed Eastward**

1037.23